

Current Open Hotel NOV issues (from Fire) January 29, 2009

04905-00001	10/12/2004	MIA HOTEL	13	Protect all vertical and horizontal penetrations in fire barriers	Tommy Weatherspoon	1/2/2009
04905-00001	10/12/2004	MIA HOTEL	13	Protect all vertical and horizontal penetrations in fire barriers	Tommy Weatherspoon	1/2/2009
08905-00034	7/31/2008	MIA Hotel	10	Provide approved access control locking arrangements for doors leading to service elevator on all floors	Tommy Weatherspoon	1/2/2009
08905-00034	7/31/2008	MIA Hotel	11	Provide current annual inspection and testing report for the fire alarm system. Report shall be clear	Carlos Tellez	03/2009
08905-00034	7/31/2008	MIA Hotel	12	Service fire alarm system to clear trouble conditions. NFPA 1: 4.5.8.1	Carlos Tellez	02/2008
08905-00034	7/31/2008	MIA Hotel	18	Provide fire sprinkler protection inside garbage chute terminal room. Submit plans for approval and obtain	Carlos Tellez	3/2009
08905-00034	7/31/2008	MIA Hotel	21	Provide fire sprinkler protection inside the service elevator machine room, electrical room, mechanical room,	Carlos Tellez	05/2009

08905-00034	7/31/2008	MIA Hotel	28	Relocate electrical conduit installation blocking sprinkler head discharge inside mechanical room del	David Caldera	05/2009
08905-00034	7/31/2008	MIA Hotel	29	Remove items stored inside center stair above 7th floor. NFPA 101: 7.1.10.1	Ray Diaz	Completed 10/2008
08905-00034	7/31/2008	MIA Hotel	30	Provide a current annual fire sprinkler system inspection and testing report. Report is to be clear	Carlos Tellez	03/2009

The following items have been reported as completed but not verified by Fire as completed or cured.

08905-00034	7/31/2008	MIA Hotel	1	Repair stair treads posing a tripping hazard in the south stairway. NFPA 1.4.5.8.1	Ray Diaz	11/2008
08905-00034	7/31/2008	MIA Hotel	3	Protect all vertical and horizontal penetrations in fire barriers. NFPA 101: 29.3.1.1.1	Ray Diaz	11/2008
08905-00034	7/31/2008	MIA Hotel	6	Provide emergency lights inside fire exit stairs or demonstrate that stair lights are powered by an	Ray Diaz	12/2008
08905-00034	7/31/2008	MIA Hotel	17	Seal/protect wall penetrations in linen chute terminal room with approved materials. NPFA 1: 4.5.8.1	Ray Diaz	11/2008

08905-00034	7/31/2008	MIA Hotel	23	Provide rated access panel on center stair floor 7 wall where a non-rated panel is attached to the wall	Ray Diaz	11/2008
08905-00034	7/31/2008	MIA Hotel	24	Remove manual door hold open device installed on the door from the center stair into the mechanical	Ray Diaz	11/2008
08905-00034	7/31/2008	MIA Hotel	25	Provide center stair to be free of openings from normally unoccupied rooms. The mechanical room	Ray Diaz	12/2008
08905-00034	7/31/2008	MIA Hotel	29	Remove items stored inside center stair above 7th floor. NFPA 101: 7.1.10.1	Ray Diaz	Completed 10/2008